

---

**2001**  
**Teck Cominco Metals Ltd.**  
**Annual Environmental Permit Report**  
**For the BC Ministry of Water, Land,**  
**and Air Protection**

Regional Manager  
Environmental Protection  
#401 - 333 Victoria Street  
Nelson, B.C.  
V1L 4K3

May 14, 2002

Attention: Mr. Carl Johnson, P. Eng.  
Head, Industrial Section

Reference:      Air Permits PA-02690, 02691 & 02692  
                        Effluent Permits PE-5309 & PE-2753

Dear Sir:

In accordance with the Letters of Transmittal accompanying Ministry of Water, Land and Air Protection permits PA-02690, PA-02691 and PA-02692 and effluent permits PE-05309 and PE-02753, the 2001 annual report is submitted.

Included in this report are summaries of the permit required ambient air monitoring data, sulphur emissions, effluent monitoring data plus all stack emission data. Also included is historical data for effluent and stack releases and for ambient air quality.

Yours truly



G.J. Gawryletz  
Group Leader, Environmental Monitoring  
Teck Cominco Metals Ltd.

Attachments:

## Reporting of **Non-detectable** data and loadings

Cominco is required to report to the ministry metal/gaseous loadings. This is determined by sample concentration multiplied by volume. When analytical methods reach their detection limits, extrapolation of the data is required to calculate a loading. When this occurs, Cominco uses one half the detection limit multiplied by the volume to calculate the loading value.

# **Section 1**

## **Air Monitoring**

### **Summary of Monitoring Results**

**Ambient SO<sub>2</sub> Concentrations**

**Sulphur Emissions**

**Production Curtailments**

**Air Permits PA-02690, PA-02691 & PA-02692**

**Sulphur/SO<sub>2</sub> Monitoring**

**Ambient SO<sub>2</sub> Monitoring**

- There were no 24 hour results that exceeded permit limits.
- There were 3 continuous hour permit exceedances results (0.30 PPM for 3 continuous hours), these 3 exceedances occurred over one 5 hour period.
- There were 4 one hour target exceedances in 2001 compared to 10 in 2000.

Correspondences for these exceedances have been previously issued to the local ministry. Refer to May 2001 Teck Cominco's monthly report and letter dated November 9<sup>th</sup> 2001 to MWLAP regarding PA 2691.

The improvement in the 1 hour target exceedances can be attributed to Zinc and Lead Operations following their SO<sub>2</sub> control procedures, as well as the extended downtime of the #2 Lead Slag Fumer furnace.

Annual averages at all sites remained relatively static with slight decreases at all stations and all were well under the annual average permit limit of 0.03 PPM.

**Sulphur/SO<sub>2</sub> Emissions**

Sulphur emissions in 2001 were down from 2000. The tonnage decrease of sulphur emissions can be attributed to the reduction in operating hours due to the three month shutdown. The Lead stack showed an increase, this was a result of flue modifications to minimize corrosive conditions that were resulting in other environmental issues.

Total annual release of SO<sub>2</sub> remained under the proposed PA-02691 and PA-02692 permit limits.

## 2001 Ambient SO<sub>2</sub> Concentrations

Station	% Time in Compliance ( ) # of excursions											
	Annual Average ppm (0.03 PPM)			Possible 365 samples 24 hr. limit (0.10 PPM)			Possible 7556 samples * 3 hr. limit (0.25 PPM)			Possible 8395 samples ** 1 hr. Target (0.34 PPM)		
	2001	2000	1999	2001	2000	1999	2001	2000	1999	2001	2000	1999
Genelle (Started June 95) <sup>2</sup>	0.005	0.006	0.004	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)
Oasis <sup>1</sup> Decommissioned Sept 2000		0.008	0.009	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	99.99 (1)
Warfield <sup>1</sup>	0.007	0.015	0.009	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (3)	100 (0)	99.99 (3)	99.99 (3)
Downtown Trail <sup>1</sup>	0.008	0.009	0.012	100 (0)	100 (0)	100 (0)	100 (0)	100 (1)	100 (0)	100 (0)	99.99 (2)	100 (0)
West Trail (Started June 95) <sup>2</sup>	0.005	0.012	0.011	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	99.99 (2)	100 (0)
Trail Hospital (Started July 95) <sup>2</sup> Out of service May to Oct 1999	0.007	0.01	0.006	100 (0)	100 (0)	100 (0)	99.96 (3)	100 (0)	100 (0)	99.95 (4)	99.99 (1)	100 (0)
Butler Park <sup>1</sup>	0.009	0.015	0.008	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	99.99 (2)	99.99 (1)
Glenmerry <sup>2</sup> Decommissioned Sept 2001	0.007	0.011	0.009	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	99.99 (1)
Columbia Gardens <sup>3</sup>	0.008	0.014	0.006	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)
Northport <sup>3</sup>	0.0004	0.002	0.002	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)	100 (0)
Total # of excursions				(0)	(0)	(0)	(3)	(1)	(3)	(4)	(10)	(6)

<sup>0</sup> W.M.B. permit required stations

<sup>2</sup> Cominco station

<sup>1</sup> W.M.B. operated station

<sup>3</sup> I.J.C. required stations

\* 3hr rolling average based on the loss of 3 three hour periods per day around the calibration hour.

Therefore 365 x 21 = 7665 periods.

\*\* 1hr averaged based on 23 hours per day x 365

### Daily Sulphur Emissions


Sulphur emissions x 2 = SO<sub>2</sub> emissions

	Tonnes/Day			% of Total		
	2001	2000	1999	2001	2000	1999
Lead Furnace Baghouse Stack	0.56	0.04	0.01	11.2%	0.9%	0.3%
#2 Slag Furnace Baghouse Stack	1.76	1.27	0.49	35.3%	29.7%	15.3%
#3 Slag Furnace Baghouse Stack	0.65	0.39	N/A	13.1%	9.13%	N/A
Zinc Stack	2.01	2.57	2.70	40.4%	60.2%	84.4%
Totals	4.98	4.27	3.20	100%	100%	100%


### Annual SO<sub>2</sub> Emissions

PA-02691	tonnes/year		
	2001	2000	1999
Lead Furnace Baghouse Stack	261	29	388
#2 Slag Furnace Baghouse Stack	512	927	1043
#3 Slag Furnace Baghouse Stack	269	285	N/A
Sub Total	1042	1241	1431
Permit Limit *	13680	13680	13680
PA-02692			
Zinc Stack	1135	1876	1960
Permit Limit	2380	2380	2380
Total	2177	3117	3391

**Cominco Limited - Trail Operations**  
**Annual Average Daily Sulphur Emissions**



Cominco Limited - Trail Operations  
Sulphur in Feed & Sulphur Emissions



**Ambient Air Monitoring**

**High Volume Particulate Samples with Metals Analyses**

**Flouride Monitoring by Impinger**

**Dustfall Monitoring with Metals Analyses**

**Flouride & Sulphation Plate Monitoring**

**Permits PA-02690, PA-02691 & PA-02692**

**Ambient Air Monitoring**

**Total Particulate & Metals by High Volume Filter Sampling**

Metals results were all slightly lower than 2000.

**Total Fluoride by Continuous Impinger Sampling**

The Warfield and Downtown stations both continue to remain well under the provincial objective.

- The Oasis site was decommissioned in September 2000
- The Glenmerry site was decommissioned in September 2001.  
As per agreement with MWLAP.

**Total Particulate & Metals by Dustfall Jar Sampling**

TSP concentration averages were under the B.C. Pollution Control Objectives for all permitted stations.

## 2001 TRAIL AREA AMBIENT AIR QUALITY

6<sup>th</sup> Day High Volume TSP Samples with Metals Analyses

B.C. Pollution Control Objectives for Airborne Particulates & Metals


	B.C. Objective Range Annual Geometric Mean					B.C. Objective Range 24 Hr. Concentration			
<b>Total Suspended Particulates</b>	60 - 70 µg/SM <sup>3</sup>					150 - 200 µg/SM <sup>3</sup>			
Lead **	1.0 - 2.5 µg/SM <sup>3</sup>					1.0 - 2.5 µg/SM <sup>3</sup>			
Zinc **	1.0 - 2.5 µg/SM <sup>3</sup>					1.0 - 2.5 µg/SM <sup>3</sup>			
Cadmium **	0.05 - 0.3 µg/SM <sup>3</sup>					0.05 - 0.3 µg/SM <sup>3</sup>			
Arsenic **	0.1 - 1.0 µg/SM <sup>3</sup>					0.1 - 1.0 µg/SM <sup>3</sup>			
<b>Ambient Air Station</b>	Annual Geometric Mean <-----µg/SM <sup>3</sup> ----->					Number and (%) of results above upper objective value			
<b>Genelle</b>	2001	2000	1999	1998		2001	2000	1999	1998
Particulates	19.90	23.03	20.70	25.97		0 (0.00%)	0 (0.00%)	0 (0.00%)	1 (1.68%)
Lead	0.07	0.10	0.11	0.09		0 (0.00%)	0 (0.00%)	0 (0.00%)	0 (0.00%)
Zinc	0.07	0.19	0.27	0.28		0 (0.00%)	1 (1.69%)	0 (0.00%)	0 (0.00%)
Cadmium	0.001	0.002	0.003	0.01		0 (0.00%)	0 (0.00%)	0 (0.00%)	0 (0.00%)
Arsenic	0.003	0.007	0.009	0.01		0 (0.00%)	1 (1.69%)	1 (1.72%)	0 (0.00%)
<b>West Trail</b>	2001	2000	1999	1998		2001	2000	1999	1998
Particulates	18.73	24.7	20.93	21.3		0 (0.00%)	1 (1.66%)	0 (0.00%)	0 (0.00%)
Lead	0.04	0.20	0.21	0.14		0 (0.00%)	0 (0.00%)	0 (0.00%)	2 (3.22%)
Zinc	0.21	0.54	0.55	0.50		1 (1.64%)	4 (6.67%)	1 (1.72%)	6 (9.68%)
Cadmium	0.003	0.007	0.010	0.01		0 (0.00%)	1 (1.66%)	0 (0.00%)	0 (0.00%)
Arsenic	0.005	0.011	0.016	0.02		0 (0.00%)	1 (1.66%)	0 (0.00%)	1 (1.61%)
<b>*** Oasis</b>	2001	2000	1999	1998		2001	2000	1999	1998
Particulates	n/a	18.5	23.62	18.1		n/a	0 (0.00%)	1 (1.72%)	0 (0.00%)
Lead	n/a	0.10	0.17	0.13		n/a	0 (0.00%)	0 (0.00%)	5 (8.33%)
Zinc	n/a	0.24	0.37	0.32		n/a	2 (4.87%)	0 (0.00%)	0 (0.00%)
Cadmium	n/a	0.003	0.006	0.01		n/a	1 (2.43%)	0 (0.00%)	0 (0.00%)
Arsenic	n/a	0.009	0.016	0.02		n/a	2 (4.87%)	3 (5.16%)	1 (1.66%)
<b>*** Warfield</b>	2001	2000	1999	1998		2001	2000	1999	1998
Particulates	n/a	26.0	20.42	25.3		n/a	2 (4.87%)	0 (0.00%)	0 (0.00%)
Lead	n/a	0.10	0.10	0.11		n/a	0 (0.00%)	0 (0.00%)	0 (0.00%)
Zinc	n/a	0.23	0.26	0.33		n/a	0 (0.00%)	1 (1.72%)	1 (1.66%)
Cadmium	n/a	0.003	0.004	0.01		n/a	1 (2.43%)	0 (0.00%)	0 (0.00%)
Arsenic	n/a	0.006	0.007	0.01		n/a	0 (0.00%)	0 (0.00%)	0 (0.00%)
<b>*** Downtown Trail</b>	2001	2000	1999	1998		2001	2000	1999	1998
Particulates	n/a	26.7	25.87	25.7		n/a	2 (4.87%)	0 (0.00%)	0 (0.00%)
Lead	n/a	0.30	0.30	0.21		n/a	1 (2.43%)	0 (0.00%)	3 (4.92%)
Zinc	n/a	0.90	0.92	0.78		n/a	6 (14.63%)	10 (17.20%)	7 (11.59%)
Cadmium	n/a	0.010	0.013	0.01		n/a	4 (9.76%)	0 (0.00%)	0 (0.00%)
Arsenic	n/a	0.015	0.020	0.01		n/a	0 (0.00%)	1 (1.72%)	1 (1.64%)
<b>*** Glenmerry</b>	2001	2000	1999	1998		2001	2000	1999	1998
Particulates	n/a	28.1	24.53	26.2		n/a	2 (4.87%)	0 (0.00%)	0 (0.00%)
Lead	n/a	0.20	0.21	0.19		n/a	0 (0.00%)	0 (0.00%)	0 (0.00%)
Zinc	n/a	0.65	0.52	0.27		n/a	2 (4.87%)	3 (5.16%)	6 (9.84%)
Cadmium	n/a	0.007	0.008	0.01		n/a	1 (2.43%)	0 (0.00%)	0 (0.00%)
Arsenic	n/a	0.018	0.019	0.01		n/a	1 (2.43%)	1 (1.72%)	1 (1.64%)
<b>*** Columbia Gardens</b>	2001	2000	1999	1998		2001	2000	1999	1998
Particulates	n/a	30	26.48	26.2		n/a	1 (2.50%)	0 (0.00%)	0 (0.00%)
Lead	n/a	0.20	0.16	0.16		n/a	0 (0.00%)	2 (3.44%)	0 (0.00%)
Zinc	n/a	0.79	0.80	0.90		n/a	0 (0.00%)	0 (0.00%)	0 (0.00%)
Cadmium	n/a	0.007	0.007	0.01		n/a	0 (0.00%)	0 (0.00%)	0 (0.00%)
Arsenic	n/a	0.008	0.010	0.01		n/a	0 (0.00%)	1 (1.72%)	0 (0.00%)
<b>*** Northport Wa.</b>	2001	2000	1999	1998		2001	2000	1999	1998
Particulates	n/a	24.6	21.6	17.0		n/a	2 (4.87%)	0 (0.00%)	0 (0.00%)
Lead	n/a	0.03	0.03	0.03		n/a	0 (0.00%)	0 (0.00%)	0 (0.00%)
Zinc	n/a	0.06	0.07	0.06		n/a	0 (0.00%)	0 (0.00%)	0 (0.00%)
Cadmium	n/a	0.001	0.001	0.01		n/a	0 (0.00%)	0 (0.00%)	0 (0.00%)
Arsenic	n/a	0.004	0.004	0.01		n/a	0 (0.00%)	0 (0.00%)	0 (0.00%)

\*\* No period defined for metals objectives


W/T & Genelle based on 61 NAPS days

\*\*\*All other stations suspended Hi-Vol sampling (03 Sept 2000)


**Trail Area Ambient Air Quality**  
**Historical Lead Averages (Geometric Mean)**  
**Genelle and West Trail**




**Trail Area Ambient Air Quality**  
**Historical Zinc Averages (Geometric Mean)**  
**Genelle and West Trail**




**Trail Area Ambient Air Quality**  
**Historical Total Particulate Averages (Geometric Mean)**  
**Genelle and West Trail**



**Trail Area Ambient Air Quality**  
**Historical Cadmium Averages (Geometric Mean)**  
**Genelle and West Trail**



**Trail Area Ambient Air Quality**  
**Historical Arsenic Averages (Geometric Mean)**  
**Genelle and West Trail**



## 2001 TRAIL AREA AMBIENT AIR DUSTFALL MONITORING

B.C. Pollution Control Objective Range 1.7 - 2.9 mg/dm<sup>2</sup>/day

Location	Average <-----mg/dm <sup>2</sup> /day----->		
	2001	2000	1999
Birchbank	0.48	0.31	0.36
Oasis	0.51	1.08	0.51
Sunningdale	0.63	0.61	0.48
Upper Duncan Flats	0.46	0.55	0.54
Lower Duncan Flats (Stoney Creek)	1.49	1.39	1.40
Warfield	0.44	0.45	0.53
Trail Hospital	0.82	0.70	0.60
Downtown Trail	0.68	0.73	0.67
Daniel Street	0.87	0.80	1.13
Glenmerry	0.82	0.75	0.81
Binns Street 242	0.94	*	*
Columbia Avenue 1428	1.59	*	*
Montrose	2.75	*	*
Northport	0.47	*	*
Shavers Bench 8th Ave	0.86	*	*
Tadanac	0.96	*	*
Trimac	0.78	*	*

Range <-----mg/dm <sup>2</sup> /day----->		
2001	2000	1999
0.14-1.97	0.17-0.42	0.14-0.88
0.09-1.16	0.21-5.94	0.24-1.13
0.28-1.60	0.17-1.66	0.28-0.98
0.19-0.79	0.29-0.90	0.35-0.88
0.42-4.69	0.28-3.52	0.47-3.76
0.21-0.90	0.21-0.66	0.19-1.09
0.26-1.76	0.24-1.18	0.28-1.13
0.25-1.11	0.50-0.92	0.40-0.87
0.29-2.19	0.31-1.66	0.26-4.59
0.24-1.62	0.35-1.56	0.19-2.86
0.35-2.48	*	*
0.69-5.55	*	*
0.28-20.39	*	*
0.23-1.07	*	*
0.46-1.35	*	*
0.15-1.90	*	*
0.24-1.41	*	*

% Compliance ( ) # > Objective		
2001	2000	1999
92 (1)	100 (0)	100 (0)
100 (0)	90 (1)	100 (0)
100 (0)	100 (0)	100 (0)
100 (0)	100 (0)	100 (0)
75 (3)	83 (2)	83 (2)
100 (0)	100 (0)	100 (0)
92 (1)	100 (0)	100 (0)
100 (0)	100 (0)	100 (0)
92 (1)	100 (0)	92 (1)
100 (0)	100 (0)	100 (0)
100 (0)	*	*
100 (0)	*	*
100 (0)	*	*
100 (0)	*	*
100 (0)	*	*
100 (0)	*	*
100 (0)	*	*

\* These sites added, as recommended by the Trail Lead Task Force, at the end of 2000.

## **2001 TRAIL AREA AMBIENT TOTAL FLUORIDE**

**7 Day Impinger samples**

**B.C. Pollution Control Objectives:**

**Total Fluoride Annual Arithmetic Mean Range 0.1 - 2.0 µg/SM<sup>3</sup>**


Ambient Air Station	Total Fluoride Annual Arithmetic Mean			
	<-----µg/SM <sup>3</sup> ----->			
Oasis	2001	2000	1999	1998
Impinger out of service Sept 2000	N/A	0.11	0.08	0.09

Warfield	2001	2000	1999	1998
	0.05	0.06	0.05	0.08

Downtown Trail	2001	2000	1999	1998
	0.10	0.11	0.08	0.12

Glenmerry	2001	2000	1999	1998
Impinger out of service Sept 2001	0.11	0.14	0.11	0.12

**Trail Area Ambient Air Quality**  
**Historical Total Fluoride Averages by Impinger Sampling (Arithmetic Mean)**  
**Warfield, Glenmerry, and Downtown Trail**



## **Stack Emission Monitoring**

**Stack Emission Monitoring - Air Permit PA-02691**

**Lead Sintering Stack (S-1)**

For emergency, and start-up/shutdown of the Kivcet Furnace, not used for normal operations.

**Lead Furnaces Baghouse Stack (S-32)**

All results under permit limits, except for the May and June tests which both exceeded the permit limit for Total Particulate Concentration. Please refer to the May and June monthly reports issued to the Ministry of the Environment for a detailed explanation.

**Slag Fuming Furnace Baghouse Stack (S-40)**

All results were under the permit limits.

**Slag Fuming Furnace Baghouse Stack (E239038)**

There are no permit limits on this stack. All results are below our internal targets.

A permit amendment has been requested for this stack.

**Refineries Scrubber Stack (R-1A)**

All results were under the permit limits.

**Lead Alloys Rotary Furnace Baghouse Stack (R-2A)**

All results were under the permit limits.

**Copper Products Flash Tank Scrubber (R-3A)**

All results were under the permit limits.

**Copper Products Ventilation Scrubber (R-4A)**

All results were under the permit limits.

**Arsenic Distillation Baghouse Stack (R-14)**

The Arsenic Distillation process did not operate in 2001.

Date: 5/10/02

Teck Cominco Metals Ltd. Trail Operations  
Lead Smelter Stack (S-32) Compliance Monitoring  
Waste Management Branch Permit PA-02691

Sample Date	Stand Volume SM3/Min	T/Part mg/SM3	T/Pb mg/SM3	T/Zn mg/SM3	T/Cd mg/SM3	T/As mg/SM3	T/Sb mg/SM3	Gas/F mg/SM3	T/Hg mg/SM3
18-Jan-01	6812	0.561	0.163	0.194	0.008	0.041	0.021	0.033	.0010
16-Feb-01	9784	4.413	0.365	0.492	0.023	0.418	0.149	0.168	.0010
27-Mar-01	8378	11.030	0.240	0.200	0.011	0.017	0.008	0.027	.0106
23-Apr-01	9102	9.640	0.854	0.604	0.032	0.048	0.111	0.030	.0109
10-May-01	9611	27.120	0.137	4.055	0.008	0.156	1.259	0.035	.0018
19-Jun-01	7997	34.790	4.290	2.570	0.068	0.190	0.028	0.058	.0030
19-Nov-01	7507	14.367	0.664	10.663	0.019	0.033	0.011	0.020	.0016
06-Dec-01	8147	6.333	0.462	0.056	0.008	0.148	0.166	0.024	.0035

Date: 5/10/01

Teck Cominco Metals Ltd. Trail Operations  
Fuming Baghouse Stack (S-40) Compliance Monitoring  
Waste Management Branch Permit PA-02691

Sample Date	Volume SM3/Min	T/As mg/SM3	T/Cd mg/SM3	T/Hg mg/SM3	T/Part mg/SM3	T/Pb mg/SM3	T/Sb mg/SM3	T/Zn mg/SM3
04-Jan-01	4727	0.183	0.016	.0009	12.038	1.894	0.145	3.650
07-Feb-01	4782	0.145	0.043	.0029	14.605	2.076	0.068	5.674
24-Oct-01	5230	0.194	0.004	.0140	4.206	0.323	0.030	1.135
09-Nov-01	4858	0.018	0.004	.0084	3.481	0.325	0.025	1.203
04-Dec-01	4743	0.020	0.002	.0014	2.090	0.222	0.018	0.452

**Teck Cominco Metals Ltd. Trail Operations**  
**Fuming Baghouse Stack (E239038) Compliance Monitoring**  
**Waste Management Branch Permit PA-02691**
Date: 5/10/02

Sample Date	Volume SM3/Min	T/As mg/SM3	T/Cd mg/SM3	T/Hg mg/SM3	T/Part mg/SM3	T/Pb mg/SM3	T/Sb mg/SM3	T/Zn mg/SM3
26-Feb-01	3853	0.107	0.001	.6680	0.850	0.040	0.006	0.180
06-Mar-01	4256	0.004	0.001	.0690	0.688	0.015	0.001	0.065
02-Apr-01	2439	0.029	0.001	1.2850	1.127	0.011	0.005	0.036
03-May-01	3625	0.171	0.004	.1190	0.398	0.014	0.020	0.035
05-Jun-01	3034	0.058	0.001	.6680	1.125	0.030	0.004	0.146
13-Nov-01	3784	0.039	0.004	.0130	2.629	0.430	0.025	1.135
05-Dec-01	3172	0.040	0.005	.0011	3.302	0.423	0.008	1.410

Date: 5/10/02

Teck Cominco Metals Ltd. Trail Operations  
Refineries Scrubber Stack (R-1A) Compliance Monitoring  
Waste Management Branch Permit PA-02691

Sample Date	Stand Volume SM3/min	T/Part mg/sm3	T/As mg/sm3	T/Pb mg/sm3	T/Sb mg/sm3	Gas/F mg/SM3
05-Jan-01	3938	5.977	0.044	0.147	0.008	0.018
09-Feb-01	3774	15.333	2.761	0.086	0.033	0.259
05-Mar-01	3672	4.363	0.018	0.035	0.058	0.016
03-Apr-01	3501	2.909	0.211	0.090	0.039	0.026
08-May-01	3458	11.276	0.106	0.139	0.186	0.561
11-Jun-01	3599	2.932	0.196	0.166	0.047	0.903
21-Nov-01	3935	2.829	0.125	0.108	0.021	0.025
12-Dec-01	3821	4.979	0.087	0.039	0.070	0.001

Cominco Ltd. Trail Operations Short Rotary Furnace Stack  
(R-2A) Compliance Monitoring  
Waste Management Branch Permit PA-02691

Date: 5/10/02

Sample Date	Stand Volume SM3/min	T/Part mg/sm3	T/As mg/sm3	T/Pb mg/sm3	T/Sb mg/sm3	Gas F mg/SM3
20-Mar-01	821	0.371	0.052	0.012	0.027	0.081
21-Jun-01	827	3.486	0.266	0.160	0.093	0.219
11-Aug-01	829	3.486	0.266	0.162	0.093	0.219

Date: 5/10/02

**Teck Cominco Metals Ltd. Trail Operations**  
**Copper Flash Tank Scrubber (R-3A) Compliance Monitoring**  
**Waste Management Branch Permit PA-02691**

Sample Date	Stand Volume sm3/min	T/As mg/sm3	T/As kg/day	T/Cu mg/sm3	T/Cu kg/day	T/Part mg/sm3	T/Part kg/day	T/Pb mg/sm3	T/Pb kg/day
23-Jan-01	43	0.062	0.004	0.050	0.003	2.080	0.13	0.017	0.001
18-Apr-01	38	0.133	0.007	0.189	0.010	3.881	0.21	0.009	0.001
14-Nov-01	37	0.062	0.003	0.427	0.023	5.681	0.31	0.017	0.001

Teck Cominco Metals Ltd. Trail Operations  
Copper Ventilation Scrubber (R-4A) Compliance Monitoring  
Waste Management Branch Permit PA-02691

Date: 5/10/02

Sample Date	Stand Volume sm3/min	T/As mg/sm3	T/As kg/day	T/Cu mg/sm3	T/Cu kg/day	T/Part mg/sm3	T/Part kg/day	T/Pb mg/sm3	T/Pb kg/day
23-Jan-01	85	0.031	0.004	0.066	0.008	0.731	0.09	0.016	0.002
18-Apr-01	114	0.111	0.018	0.234	0.038	1.851	0.30	0.006	0.001
14-Nov-01	129	0.003	0.001	0.200	0.037	1.293	0.24	0.004	0.001

**Stack Emission Monitoring - Air Permit PA-02692**

**Main Zinc Stack (Z-1)**

All results were under the permit limits.

**Zinc Melting Plant Baghouse Stack (EM-1)**

All results were under the permit limits.

**Zinc Melting Plant Atomized Zinc Dust Stack (EM-3)**

All emission results under permit limits. The Standard volume exceeded permit limit of 170 sm<sup>3</sup>/minute, actual reading was 180sm<sup>3</sup>/minute. Restricting the volume while ensuring adequate ventilation corrected this problem.

Teck Cominco Metals Ltd. Trail Operations  
Zinc Stack (Z-1) Compliance Monitoring  
Waste Management Branch Permit PA-02692

Date: 5/10/02

Sample Date	Stand Volume SM3/min	T/Cd mg/sm3	T/Hg mg/sm3	T/Part mg/sm3	T/Pb mg/sm3	T/Zn mg/sm3	T/NH3/N mg/sm3
08-Jan-01	3795	0.006	.0340	21.62	0.108	0.214	2.130
01-Feb-01	3838	0.003	.0634	15.96	0.039	0.157	6.868
19-Mar-01	2608	0.004	.2246		0.046	0.230	5.087
04-Apr-01	3376	0.004	.0681	44.90	0.023	0.349	3.502
04-May-01	3566	0.002	.0687	19.13	0.008	0.089	2.571
01-Jun-01	3709	0.003	.0334	38.86	0.024	0.173	3.664
15-Oct-01	2894	0.005	.6576	59.34	0.052	0.357	9.975
02-Nov-01	3670	0.003	.0460	21.04	0.037	0.253	3.304
07-Dec-01	4392	0.003	.0874	33.63	0.419	0.209	5.239

Date: 5/10/02

Teck Cominco Metals Ltd. Trail Operations  
E & M Zinc Main Stack (EM-1) Compliance Monitoring  
Waste Management Branch Permit PA-02692

Sample Date	Stand Volume SM3/min	T/Part mg/sm3	T/Zn mg/sm3
29-Nov-01	1950	0.771	0.178

Teck Cominco Metals Ltd. Trail Operations  
E & M Zinc Atomizer Stack (EM-3)  
Compliance Monitoring  
Waste Management Branch Permit PA-02692

Date: 5/10/02

Sample Date	Stand Volume SM3/min	T/Part mg/sm3	T/Zn mg/sm3
23-Feb-01	180	48.66	34.99

Stack Emission Monitoring - Air Permit PA-02690

Ammonia Sulphate Plant:

Oslo Vent (W-1), Centrifuge Vent (W-2), Dustabator (W-3), and #1 Dryer (W-4)

All results were under their permit limits.

Fertilizer Storage Plant:

#1 Mill (W-6) and #11 Mill (W-8)

The above sources were under their permit limits.

A permit amendment requesting a wording correction to better reflect that each source has a stack and requires separate permit limits.

#2 Mill (W-7) and #13 Mill (W-10), and #14 Mill (W-12)

All results were under their permit limits.

Granular Ammonium Sulphate Plant:

Gas Cooler (W-46), Gas Baghouse (W-70), Gas Scrubber (W-71)

All results were under their permit limits except for the Granular baghouse (W-70), and the Granular plant Scrubber Stack (W-71), both of which exceeded the permit limit for Total Particulate.

Following these tests, an inspection was performed on the baghouse, faulty bags were replaced, followed by a stack test, which results were 78.3 mg/sm<sup>3</sup>, well below permit limits.

Maintenance was performed on the Scrubber, followed by a stack tests, which results were 33.5 mg/sm<sup>3</sup>, well below permit limits.

TeckCominco Metals Ltd.  
 Trail Fertilizer Operations Emission Tests - 2001  
 Waste Management Branch Permit PA-02690

**Ammonium Sulphate Plant**

<b>W-1 Oslo Vent</b>	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	226	115	
WMB Frequency	A	A	
Not operational in 2001	n/a	n/a	n/a

<b>W-2 Centrifuge Vent</b>	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	238	115	
WMB Frequency	A	A	
Not operational in 2001	n/a	n/a	n/a

<b>W-3 Dustabator</b>	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	481	290	
WMB Frequency	SA	SA	
Date	22-Jan-01	322	18.9
Date	22-Nov-01	318	65.3

<b>W-4 #1 Dryer</b>	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	569	290	
WMB Frequency	SA	SA	
Date	27-Feb-01	187	4.1
Date	20-Nov-01	281	5.3
			2.1

TeckCominco Metals Ltd.  
 Trail Fertilizer Operations Emission Tests - 2001  
 Waste Management Branch Permit PA-02690

Fertilizer Storage Plant

W-6 #1 Mill	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	350 *	200	
WMB Frequency	A	A	
Date	11-Jan-01	167	75.5      18.2

W-7 #2 Mill	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits			
WMB Frequency	A	A	
Not operational in 2001			

W-8 #11 Mill	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	350 *	200	
WMB Frequency	A	A	
Date	02-Feb-01	192	171.34      47.43

\* Volume limit is total of W-6 & W-8

W-10 #13 Mill	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	282	350	
WMB Frequency	A	A	
Date	10-Jan-01	141	0.13      0.03

W-12 #14 Mill	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	
Permit Limits	141	350	
WMB Frequency	A	A	
Date	11-Jan-01	132	0.5      0.1

TeckCominco Metals Ltd.  
 Trail Fertilizer Operations Emission Tests - 2001  
 Waste Management Branch Permit PA-02690

**Granular Ammonium Sulphate Plant**

The following emission sources were not in service during 2001


W-01	Oslo Vent
W-02	Centrifuge Vent
W-28	Salt Bin Baghouse
W-30	Rock Bin Baghouse
W-34	#1 Clarifier Vent
W-35	#2 Clarifier Vent
W-36	#3 Clarifier Vent
W-39	#2 Acid Feed Tank
W-40	#3 Acid Feed Tank
W-41	#4 Acid Feed Tank
W-43	#10 Impinger
W-44	#30 Impinger
W-45	#1 Fertilizer Stack
W-47	#3 Fertilizer Stack
W-54	Filter Vent Scrubber
W-55	Filter Vacuum Pump
W-56	Reactor Vent Scrubber
W-57	Cooler Vacuum Pump

W-46 GAS Cooler	Volume SM <sup>3</sup> /min.	Total Particulate		NH <sub>3</sub>	
		mg/SM <sup>3</sup>	kg/24Hrs.	mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	1000	46			
WMB Frequency	A	A		A	
Date	27-Nov-01	725	12.4	13.0	1.4
					1.5


W-70 GAS Baghouse	Volume SM <sup>3</sup> /min.	Total Particulate	
		mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	700	125	
WMB Frequency	A	A	
Date	27-Nov-01	673	166.3
			161.1

W-71 GAS Scrubber	Volume SM <sup>3</sup> /min.	Total Particulate		NH <sub>3</sub>	
		mg/SM <sup>3</sup>	kg/24Hrs.	mg/SM <sup>3</sup>	kg/24Hrs.
Permit Limits	2000	46			
WMB Frequency	SA	SA		SA	
Date	11-Apr-01	1002	30	43	718
					1036
Date	27-Nov-01	971	79	110	507
					708


**Cominco Limited - Trail Operations**  
**Annual Average Daily Total Particulate Emissions**




**Cominco Limited - Trail Operations**  
**Annual Average Daily Total Lead Emissions**




**Cominco Limited - Trail Operations**  
**Annual Average Daily Total Zinc Emissions**




**Teck Cominco Metals Ltd - Trail Operations**  
**Annual Average Daily Total Cadmium Emissions**




**Cominco Limited - Trail Operations**  
**Annual Average Daily Total Mercury Emissions**



**Cominco Limited - Trail Operations**  
**Annual Average Daily Total Arsenic Emissions**



**Cominco Limited - Trail Operations**  
**Annual Average Daily Total Fluoride Emissions**



## **Effluent Monitoring Summary & History**

**Effluent Permits PE-02753, PE-05309**

**Effluent Monitoring - PE-02753**

Detailed explanations were written to MWLAP for each of the following noted exceedences.

**Combined Outfall II**

Slight reductions in Arsenic and Zinc concentrations. All metals loading showed slight decreases except for total Arsenic, which showed a slight increase.

There were 3 effluent permit limit exceedences for the year; 2 dissolved Zinc loading and 1 dissolved Zinc concentration.

**Combined Outfall III**

Annual averages from this source showed decreases for concentration and loading for all elements except for Arsenic and Antimony. Both showed increases in Dissolved and Total results in concentration and in loading.

There were 6 effluent permit limit exceedences for the year; 3 dissolved Zinc and 1 dissolved Cadmium concentration, 1 dissolved Zinc concentration, and 1 total Mercury loading.

**Effluent Monitoring - PE-05309**

**Combined Outfall IV**


Annual averages from this source showed decreases for concentration and loading for all elements from 2000. There were 2 permit limit exceedences for the year; both for pH.

**LC 50 Monitoring PE-02753 and PE-05309**


Outfall II passed 2 of the 4 quarters.  
Outfall III passed 4 of the 4 quarters.  
Outfall IV passed 3 of the 4 quarters.

Explanations for the failed tests were provided within the Teck Cominco monthly report to the local MWLAP.


**Teck Cominco Metals Ltd.Total & Dissolved Zinc  
All Metallurgical Outfalls**




**TeckCominco Metals Ltd. Total & Dissolved Lead  
All Metallurgical Outfalls**




## Teck Cominco Metals Ltd Total & Dissolved Cadmium All Metallurgical Outfalls




**TeckCominco Metals Ltd. Total & Dissolved Arsenic  
All Metallurgical Outfalls**




**TeckCominco Metals Ltd. Total & Dissolved Copper  
All Metallurgical Outfalls**




**TeckCominco Metals Ltd.Total Mercury  
All Metallurgical Outfalls**




**TeckCominco Metals Ltd. Trail Fertilizer Operations**  
**Annual Average Daily NH<sub>3</sub>/N Discharge**



**TeckCominco Metals Ltd. Trail Fertilizer Operations**  
**Annual Average Daily Diss/SO<sub>4</sub> Discharge**



**TeckCominco Metals Ltd. - Trail Fertilizer Operations**  
**Annual Average Daily Dissolved Zinc Discharge**



**TeckCominco Metals Ltd.Total Mercury  
Fertilizer Outfall**

